

# Bell 430 Series Alert Service Bulletin Status

Registration: N430TX

Aircraft TT: 2855.3

Serial Number: 49005

Date: 8-Nov-07

Bulletin Number	Rev. No.	Subject	Applicable AD Note	Method of Compliance	Recurring		Complied With		Next Due		Signature & Certificate
					Yes	No	Date	Hours	Date	Hours	
ASB 430-07-41	C	Tail Rotor Blade Assembly	AD 2007-19-52	Inspect		XX	7-Nov-07	2855.3			T.Williams A&P 2119807
ASB 430-07-40		Disk Pack Assembly P/N 36300-1 & 37855-1		Inspect per part II		XX	7-Nov-07	2855.3			T.Williams A&P 2119807
ASB 430-07-39		Tail Rotor Pitch Change Mechanism		Revised rigging procedures		XX	7-Nov-07	2855.3			T.Williams A&P 2119807
ASB 430-06-38		Engine Turbine PT Outer Shaft, CEB-A-72-5052		Check & replace	XX		7-Nov-07	2855.3	NA by shaft serial number (both engines)		T.Williams A&P 2119807
ASB 430-06-37		Engine Power Assurance & Overhauled Transmission Run-In Procedure		Introduction by installing RFM supplement	XX		7-Nov-07	2855.3			T.Williams A&P 2119807
ASB 430-05-36		Engine HMU P1 Nozzle Screen, CEB-A-73-5033		Check during each preflight	XX		16-Sep-05	2734.5	-	-	HAS GS1R177K
ASB 430-05-35		AFCS Air Data Computer, VNE Overspeed Warning Computer Airspeed indicator & VNE converter		Installed diode per Part II		XX	26-Jun-07	2852.6			TAS RV1R466K
ASB 430-05-34		Recording of threshold events & steady-state ops avoidance limits, CEB-A-72-5048 & AD 2006-20-07		Install placard		XX	16-Sep-05	2734.5			HAS GS1R177K
ASB 430-05-33		Servo Actuator-to-Actuator Support Bolts		Introduce retirement life		XX	16-Sep-05	2734.5			HAS GS1R177K
ASB 430-04-32	B	Tail Rotor Counterweight Bellcrank P/N 222-012-727-105		Replacement		XX	7-Nov-07	2855.3	Requirements met by compliance with AD 2006-13-14 by TAS		T.Williams A&P 2119807
ASB 430-04-31	B	Tail Rotor Blades P/N 222-016-123 & -131	AD 2005-04-06 (c)	50hr inspection per Part II	XX		-	2852.6	-	2902.6	Carried on inspection status sheet
ASB 430-04-30	C	Tail Rotor Counterweight Bellcrank P/N 222-012-727-003	AD 2006-13-14	Replacement		XX	26-Jun-07	2852.6			TAS RV1R466K
ASB 430-03-29		Rolls-Royce 250-C40B, 4th Stage Turbine Wheels, CEB-A-72-5043		Replacement		XX	7-Nov-07	2855.3	NA by wheel serial number (both engines)		T.Williams A&P 2119807
ASB 430-03-28		Airspeed Limitations		Revision		XX	13-Jun-03	1797.6			HAS GS1R177K
ASB 430-03-27		Electrical Power Feeders		Modify		XX	16-Feb-05	2371.8			HAS GS1R177K
ASB 430-02-26		Landing Gear Wheel & Brake Hydraulic Tubes		Replacement		XX	19-Jun-02	1515.7			A&P 38343145
ASB 430-02-25		Fuel System Check & relief Valve P/N 222-366-687-101		Replacement		XX	13-Aug-02	1535.1			A&P 0225223451
ASB 430-02-24		FADEC-ECU Power Supplies		Isolation		XX	19-Jun-02	1515.7			A&P 38343145
ASB 430-01-23		Main Rotor Drive Hub P/N 430-010-410-101		Inspection & recall		XX	29-Aug-01	1438.8			A&P 38343145
ASB 430-01-22		Temporary Ambient Air Temperature Limitation		Remove		XX	5-Jun-01	1391.3			A&P 38343145
ASB 430-01-21		Upper RH Fuel Enclosure Drain Provision		Add		XX	30-Mar-01	1344.8			A&P 38343145
ASB 430-01-20		Swashplate Duplex Bearing P/N 430-310-450-101		Retorque per Part II, 150hrs		XX	30-Mar-01	1344.8			A&P 38343145
ASB 430-01-19	A	Electrical System Improvements		Incorporate		XX	16-Oct-01	1448.0			A&P 38343145
ASB 430-00-18	A	Rolls-Royce 250-C40B, Compressor Scroll P/N 23066737 & 23072848, CEB-A-72-5028		Replacement		XX	13-Jan-01	1222.9	NA by P/N		HAS GS1R177K
ASB 430-00-17		Hydraulic Actuator Support P/N 222-040-125-001		Inspect		XX	15-Jun-00	1088.6			A&P 38343145

# Bell 430 Series Alert Service Bulletin Status

Registration: N430TX

Aircraft TT: 2855.3

Serial Number: 49005

Date: 8-Nov-07

Bulletin Number	Rev. No.	Subject	Applicable AD Note	Method of Compliance	Recurring		Complied With		Next Due		Signature & Certificate
					Yes	No	Date	Hours	Date	Hours	
ASB 430-00-16		Improved Instrument Panel Cooling		Incorporate		XX	13-Jan-01	1222.9			HAS GS1R177K
ASB 430-00-15		Rolls-Royce 250-C40B, Self-Sealing magnetic Chip Detectors, CEB-A-72-5027		Inspect		XX	13-Jan-01	1222.9	Not Installed		HAS GS1R177K
ASB 430-99-14		Chapter 4 Airworthiness Limitations Schedule Changes		Incorporate		XX	-	-	-	-	Incorporated into maintenance manual
ASB 430-99-13		Fuel Quantity Indication System		Calibrate		XX	11-Nov-00	1219.6			A&P 38343145
ASB 430-99-12		Tail Rotor Pitch Change Bearings P/N 222-312-753-103 & Tail Rotor Attaching Hardware		Replacement		XX	13-Jan-00	974.5			A&P 38343145
ASB 430-99-11		Auto Pilot Resolver Installation		Improvement		XX	30-Sep-99	917.2			A&P 38343145
ASB 430-99-10		Electrical Power Distribution System		Modify		XX	13-Jan-01	1222.9			HAS GS1R177K
ASB 430-99-9		Swashplate Duplex Bearing P/N 430-310-450-101		Inspect		XX	17-Mar-99	778.4			A&P 38343145
ASB 430-98-8		Damper Blade Set P/N 430-310-104-105		Introduction		XX	12-Apr-99	790.6			A&P 38343145
ASB 430-98-7		Pilot & Copilot Static System		Modify		XX	23-Feb-99	743.0			Premier Aviation IPTR140L
ASB 430-98-6		Lateral Control Tube P/N 430-001-018-101 & Forward Fairing P/N 430-061-822-101		Replace tube & rework fairing		XX	23-Feb-99	743.0			Premier Aviation IPTR140L
ASB 430-98-5		Vertical Fin Installation		Modify per Part II		XX	23-Feb-99	743.0			Premier Aviation IPTR140L
ASB 430-98-5		Vertical Fin Installation	AD 99-23-03	Torque check per Part III	XX		-	-	-	-	Incorporated into maintenance manual
ASB 430-97-4		Temporary Air Speed Restriction & Damper Yoke Set P/N 430-310-100-101 & 430-310-107-101		Remove restriction & replace dampers		-	-	-	-	-	Superseded by ASB 430-98-8
ASB 430-97-3		FADEC-ECU Fail and Retractable Landing Gear Indicating Systems		Modify systems		XX	19-Nov-97	427.0			A&P 38343145
ASB 430-98-2		Temporary Airspeed Restriction		Incorporate		XX	27-Jul-09	301.6			A&P 38343145
ASB 430-98-1		Rolls-Royce 250-C40B, Operational Restrictions and PTO Gears P/N 23056617, CEB-A-72-5009		Replace gear		XX	Entry in cover of #1 log book, no time or date.				Complied with as AD 97-25-09. See engine records

Blue = Recurring Compliance

Red = Pending Compliance